

**5th event of Lithuanian automobile Rally Sprint Championship/ Lietuvos automobilių ralio
sprinto čempionato V-as etapas**

Steward Decision

Time:

Starting number 69, during last rally sprint event “Viekšniai 2017” was warned for not mounting ventilation panels in side windows.

During 5th event of Lithuanian automobile Rally Sprint Championship, by the report of Chief Scrutineer, their car still did not have above mentioned ventilation panels. This is the breach of Supplementary Regulations 1.1 article and 2017 national technical regulations for group “L”: 7.3 article “h” part : for safety measures in both sides of plastic side windows must be mounted ventilation panels.

Steward Decided to levy a penalty of 100EUR.

Steward

Arnas Paliukėnas

Understood , about opportunity to appeal
and about appeal procedure I am informed.

Crew nr.:
Signature:

Time: